


Pipe Graphic Report of PLR S13MM_039MH X for Baltimore City


Setup 1857	Surveyor ADS-BY	Certificate # U307-04-4765	System Owner BALTIMORE CITY DPW
Drainage HL-28	Survey Customer P0310		
P/O # 13MM	Date 2008/11/04	Time 8:34	Street ASHBURTON ST 2221
City BALTIMORE	Further location details		
Start S13MM_041MH	Rim to invert 21.80	Grade to invert	Rim to grade Ft
Finish S13MM_039MH	Rim to invert 20.00	Grade to invert	Rim to grade Ft
Use Sanitary	Direction Upstream	Flow control Not Controlled	Media No HL-P042
Shape Circular	Height 18 Width ins	Preclean J	Year Cleaned 2008/11/03
Material Vitrified Clay Pipe	Joint length 2.5 Ft	Total length 521.0 Ft	Length Surveyed 520.30
Lining	Year laid	Year rehabilitated	Weather Dry
Purpose Routine Assessment	Cat		
Additional info		Structural	O&M
Location Light Highway		Miscellaneous	Hydraulic
			Constructional



PipeLogix Inc.
Phone: 866-299-3150
Fax: 760-406-6023

Pipe Graphic Report of PLR S13MM_039MH X for Baltimore City

Setup 1857	Surveyor ADS-BY	Certificate # U307-04-4765	System Owner BALTIMORE CITY DPW
Drainage HL-28	Survey Customer P0310		
P/O # 13MM	Date 2008/11/04	Time 8:34	Street ASHBURTON ST 2221
City BALTIMORE	Further location details		
Start S13MM_041MH	Rim to invert 21.80	Grade to invert	Rim to grade Ft
Finish S13MM_039MH	Rim to invert 20.00	Grade to invert	Rim to grade Ft
Use Sanitary	Direction Upstream	Flow control Not Controlled	Media No HL-P042
Shape Circular	Height 18 Width ins	Preclean J	Year Cleaned 2008/11/03
Material Vitrified Clay Pipe	Joint length 2.5 Ft	Total length 521.0 Ft	Length Surveyed 520.30
Lining	Year laid	Year rehabilitated	Weather Dry
Purpose Routine Assessment	Cat		
Additional info		Structural	O&M
Location Light Highway		Miscellaneous	Hydraulic
		Constructional	



PipeLogix Inc.
Phone: 866-299-3150
Fax: 760-406-6023